



Cables



LEMO-Connector
Solder side

IMPORTANT !!!!!!!

- The shield must be isolated from the housing of the LEMO-Connector.
- Always mount the shield on the LEMO- Connector – never on the pickup-arm.